



American Energy Corporation

43521 Mayhugh Hill Road
Beallsville OH, 43716

5F Table Referring To Map 5E

5Fi		5Fii		5Fiii				5Fiv	5Fv		5Fvi	5Fvii	5Fviii	
Outfall Numbers		NPDES Point	NPDES Permit No.	Application No.	Issue Date	Effective Date	Expiration Date	Description	Latitude	Longitude	Receiving Water	How Conveyed to Receiving Water	Discharge Located Within 500 Yards Upstream of Water Supply Intake	
Outfall 001		P-001	Yes	OGM00142*BG	#1363	August 8, 1994	August 1, 2009	July 31, 2014	Sedimentation discharge from reclaimed area.	39° 54' 06"	81° 01' 06"	Piney Creek	Rock Channel	No
Outfall 002		P-002	Yes	OGM00142*BG	#1363	August 8, 1994	August 1, 2009	July 31, 2014	Sedimentation discharge from reclaimed area.	39° 54' 16"	81° 00' 55"	Piney Creek	Rock Channel	No
Outfall 018		P-018	Yes	OGM00142*BG	#1363	August 8, 1994	August 1, 2009	July 31, 2014	Final effluent discharge from raw and clean coal piles as well as preparation plant. Sample to be taken from discharge pipe prior to entering Piney Creek.	39° 54' 11"	81° 01' 18"	Piney Creek	Rock Channel	No
Outfall 002		P-002	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Final effluent from treatment pond receiving pumped water from the underground mine works. Sample to be taken from discharge spillway prior to entering Piney Creek.	39° 53' 36"	81° 01' 19"	Piney Creek	Ditch	No
Outfall 008		P-008	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Raw and clean coal storage pile and prep plant area pond final effluent. Sample to be taken from discharge spillway prior to entering Piney Creek.	39° 53' 52"	81° 01' 13"	Piney Creek	Rock Spillway	No
Outfall 011		P-011	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Office/bath house, parking lots, supply yard, portal, and conveyor area treatment pond final effluent. Also receives discharge water from 601 and pumped mine water from underground mine works. Sample to be taken from discharge pipe prior to entering Piney Creek.	39° 53' 48"	81° 01' 19"	Piney Creek	Rock Spillway	No
Outfall 012		P-012	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Coal refuse pile disposal spillway prior to entering Piney Creek.	39° 53' 52"	81° 01' 13"	Pond 8	Rock Channel	No
Outfall 013		P-013	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Coal refuse disposal site treatment pond final effluent, sample to be taken from discharge spillway prior to entering Piney Creek.	39° 53' 52"	81° 01' 28"	Piney Creek	Grass Channel	No
Outfall 014		P-014	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Coal refuse disposal site treatment pond final effluent. Sample to be taken from discharge spillway prior to entering an unnamed tributary of Piney Creek.	39° 53' 58"	81° 01' 45"	Piney Creek	Rock Channel	No
Outfall 015		P-015	Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Coal refuse disposal site treatment pond final effluent. Sample to be taken from discharge pipe prior to entering unnamed tributary of Captina Creek.	39° 54' 14"	81° 01' 54"	Captina Creek	Pipe	No
Outfall 017	Sewage Plant		Yes	OIL00091*GD	OH0059552	October 7, 2002	December 1, 2002	July 31, 2007	Main office/bath house sanitary wastewater treatment plant (WWTP) discharge. Sample to be taken from discharge pipe prior to entering Piney Creek.	39° 53' 44"	81° 01' 25"	Piney Creek	Pipe	No

CWA Section 308
I. Instructions
9. Documents and persons consulted examined or referenced

Referenced Documents
NPDES Permit OIL00091*GD
General NPDES: OHM000003 / OGM00142*BG
SMCRA Permit D-1159
SMCRA Permit D-0425
Application for NPDES renewal can be found in 5D

Persons Consulted
Populated Original Response Dennis Dubiel
Reviewer: Cody Mozena
Reviewer: Drew Hudson
Reviewer: Dave Washinsky
Reviewer: Crellin Scott

Environmental consultants contracted for preparation and submittal of the referenced documents.
Hamilton and Associates